Certificate of Location of Government Corner

ID#: 650906 **Description:** 1/4 SEC COR 8 9 65 **Date Set:** 5/13/1977 **County:** Olmsted

Section: 09 **Township:** 106N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in a cultivated field
The monument is down 1'
Post w/sign 2' north
This corner is located by GPS measurement

Corner History:

6-7-1854 Michael G. Karrick, Deputy Surveyor, measured north 40.00 chains between Sections 8 and 9. Set quarter section post. RPs - 12" Bur Oak N15°W 127 links (83.82'), 14" Bur Oak N17°E 161 links (106.26').

12-6-1870 Robert Perry, County Surveyor, (Book A, Page 137, Survey No. 166), found original NW bearing tree standing. Set temporary point to run east-west quarter line of Section 9.

5-21-1873 Thomas Hunter, County Surveyor, (Book A, Page 225, Survey No. 228), "found old original 1/4 post standing in the ground, but it was claimed to have been moved or at least stuck up at random as it was seen lying on the ground, some distance from where it now sticks." Reset stake from NW bearing tree. Ran line from the NW Corner Section 9 to the SW Corner Section 9 and found the stake as set to be 3 links (1.98') west of line. 1/16th North set stake midway and on line at 19.87 chains (1311.42'). 1/16th South set stake midway and on line at 19.98 chains (1318.68').

5-13-1977 County Survey Crew dug for corner and found nothing. Set Cast Iron Cap on 2' telspar pipe down 1' at prorated Thomas Hunter measure and 3 links (1.98') west of line. The corner falls in a cultivated field.

5-13-2002 County Survey Crew found Cast Iron cap on telspar pipe down 1' in good condition and measured its position using GPS. Set post w/sign 2' north.