# Certificate of Location of Government Corner

**ID#:** 651006 **Description:** 1/4 SEC COR 9 10 65 **Date Set:** 5/12/1977 **County:** Olmsted

**Section:** 10 **Township:** 106N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

**Reference Ties:**

The corner falls 8' north of fence east and 16' west of fence north
The monument is down 1'
Steel post NE 18.77'
Spike in CP SE 18.0'
This corner is located by GPS measurement

**Corner History:**

6-6-1854 Michael G. Karrick, Deputy Surveyor, measured north 40.00 chains between Sections 9 and 10. Set quarter section post in mound with trench, pits, charred stake and planted Osage Orange seeds NE and SW.

12-6-1870 Robert Perry, County Surveyor, (Book A, Page 137, Survey No. 166), found old post corner standing in mound. 1/16th South found old post set by him in a previous survey.

5-21-1873 Thomas Hunter, County Surveyor, (Book A, Page 225, Survey No. 228), found old original quarter post standing in mound. 1/16th North set stake midway and on line at 19.90-1/2 chains (1313.73').

5-1977 County Survey Crew dug with backhoe and found a stake hole running down into the clay.

5-12-1977 Roger Brand, County Surveyor, accepted the stake hole as the corner location. County Survey Crew set Cast Iron Cap on 2' telspar pipe down 1' at stake hole location. The corner falls 8' north of fence east and 16' west of north-south fence. RPs - Spike in corner post SE 18.0', Steel fence post NE 18.77'.

5-13-2002 County Survey Crew found Cast Iron Cap on telspar pipe down 1' in good condition and measured its position using GPS.