Certificate of Location of Government Corner

ID#: 651106 **Description:** 1/4 SEC COR 10 11 65 **Date Set:** 7/17/2006 **County:** Olmsted

Section: 11 **Township:** 106N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

Steel post w/PVC pipe 1' north
Post w/sign 2' E
This corner is located by GPS measurement

Corner History:

6-1854 Michael Karrick 40.00 set quarter section post in mound with trench, pits, cahrred stake and Osage Orange seeds NE & SW.

6-7-1984 County Surveyor dug for corner. There were many boulders in the first 1' of fill in the fence line above the natural ground. Beneath the boulders we found a cedar post stub running down to 4 1/2' deep and packed in small boulders. As we scraped down the wall of the hole around the post stub we found the old stake mark with some wood pieces remaining. The top of the stake was down 2' and ran down another 1 1/2' with a long tappered point. The top part of the stake appx 3" diam. We found nothing further in the dig so accepted the stake at the Gov't corner and set a CIM over a 5/8" x 3' re-rod at its location.

2-8-2005 County Surveyor found CIM leaning west down 0.1' in cultivated field. Sign and post along SE side of CIM and steel post WNW. Farmer has been plowing around the posts but all fences are gone.

7-17-2006 County Surveyor found CIM at surface leaning west. Removed CIM and found 5/8" rerod down 1.6' in good condition. Removed 5/8" rerod and set 5 1/2' telspar pipe w/cast iron cap at surface packed in stones at 5/8" rerod position.