Certificate of Location of Government Corner

ID#: 651205 **Description:** SEC COR 11 12 13 14 65 **Date Set:** 5/17/2006 **County:** Olmsted

Section: 12 **Township:** 106N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The cast iron cap in telspar pipe is down 0.5'
The corner falls 2' west of centerline of N-S twp road and 3 1/2' south of center of E-W twp road
County Survey Disk in top of RR tie SW 43.85'
County Survey Disk in NE side PP #8078 SE 43.76'
This corner is located by GPS measurement

Corner History:

8-1856 T. Hunter Bk. A Pg.15 did some measureing, West 2610.3' East 2612.14 with 1/16th stake North 2616.24 with 1/16th stake.

4-1911 C. Larson Bk. B Pg. 154 found the stake as the corner and set a boulder 4"x12"x18'. Set a stone as the 1/16th stone West at 1305.15'.

6-13-1972 County Surveyor set CIM over stake found and 1" x 18" pipe and silverware etc.

5-16-1978 County Surveyor dug 4x6x18 hole by 4' deep to clay. Found nothing. Hit old culvert at one point we wanted to look which would be at Hunter's 1856 measure from 1/4 cor. 12-13 plus 26' but covered point at double the line and measure from 1/4 cor 11-14 (as set in 76) over the stake found at the 1/16th East.

11-8-2002 County Surveyor found CIM without head in good condition.

5-17-2006 County Surveyor found CIM with head broken down 0.7', took local ties and removed. Found 1"x18" pipe in good condition down 2.3', ties matched, removed. Set 5' telspar w/CIC from ties taken from CIM down 0.4'. CSD with concrete nail in top of vertical RR tie SW 43.85', removed old tie in PP (too low) and set new CSD with concrete nail in NE side of PP 8078 SE 43.76'.

2-19-2010 County survey crew found cast iron cap on telspar pipe down 0.5" in good condition