Certificate of Location of Government Corner

ID#: 651304 **Description:** 1/4 SEC COR 13 24 65 **Date Set:** 6/28/1978 **County:** Olmsted

Section: 13 **Township:** 106N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 19 1/2' east of centerline of CSAH 15 on curve and 2' south of fence east
This corner is located by GPS measurement

Corner History:

6-1854 Gov't Notes M. Karrick, Deputy Surveyor West on true line between sections 13 and 24. 40.00 chs. Set quarter section post. Burr Oak 12 in. S55°W 154 lks. Dug trench. 80.00 chs. Selection corner.

7-1872 Thomas Hunter, County Surveyor, (Book A P.200 No.209) could not find this corner. Set the corner midway and on line between the section corners.

8-30-1973 County Surveyor. This corner comes in a rock cut area of Co. Rd. 15 and would be gone entirely. Set a 3/4" rod midway and on line between the section corner as in Survey No. 209.

6-28-1978 County Surveyor set a Cast Iron Cap on a square pipe 25" over the rod set in 1973. Should check the possibility that Hunter had his 72' bad chain in survey # 209 which would move this corner 8 to 10' E to center of rd N. Run N-S 1/4 line 24 and look for 1/4 cor. 18-19 Roch. Corner is 2' south of the fence east.

7-21-2006 County Surveyor found cast iron cap on telspar pipe down 0.1' in good condition. Monument falls just off of shoulder in slope for east side of CR 15.

10-4-2006 County Surveyor found cast iron cap on telspar pipe down 0.2' in good condition.