Certificate of Location of Government Corner

ID#: 651404 **Description:** 1/4 SEC COR 14 23 65 **Date Set:** 10/24/1973 **County:** Olmsted

Section: 14 **Township:** 106N **Range:** 15W **Monument Description:** Cast Iron Monument

Reference Ties:

The CIM is down 0.9'
The corner falls 1 1/2' east of fence south, 1' north of fence west and 1 1/2' ENE of CP
Post w/sign 2' south
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes M.G. Karrick, Deputy Suveyor West on true line sections 14 and 23. 40.00 chs. Set quarter section post. Burr Oak 15 in. N50°E 74 lks. Burr Oak 13 in. S44°W 205 lks.

6-1874 Thomas Hunter (P.254 No.254), found stake standing and stump of S.W. bearing tree also.

12-1894 William Fraser (P.562 No.516), County Surveyor, used corner fence post for line
South.

4-1911 Chas. Larson (P.154B) no mention of corner or 1/16 corners either East or West. Plat shows West 19.95.5 M&L and East 20.01 M&L with 1/16 corner numbered but not described or mentioned.

10-24-1973 County Surveyor dug and found nothing. Reset corner using east-west fence for north-south control intersected by the North-South 1/4 line of Section 23. Set a C.I.M. over a 5/8" iron rod at the location as corner.

2-23-2010 County survey crew found CIM down 0.9' in good condition.