Certificate of Location of Government Corner

ID#: 651606 **Description:** 1/4 SEC COR 16 17 65 **Date Set:** 9/7/2001 **County:** Olmsted

Section: 16 **Township:** 106N **Range:** 15W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 1/2' south of centerline of CSAH 25
County highway disk in fence post S 22.05'
County highway disk in PP N 31.40'
NE corner of basement SE 97.75'
County Survey Disk in PP N 47.73'
Punch hole in 24" CMP w/apron SE 63.81'
Ref pipe N 55.63'
This corner is located by GPS measurement

Corner History:

6-1854 Michael Karrick 4.50 creek 7 lks wide runs SW. 21.70 same runs SE and leave timber bears NW. 40.00 set quarter section post in mound with trench, pits, charred stake and Osage Orange seeds NE & SW.

1-1870 R. Perry Pg.90. No.134 set large stone as 1/4 corner

1-1891 T. Fraser Pg.449 No.433 found boulder

5-1893 W. Fraser Pg.510 No.478 found stone

6-1935 J. Kerr Bk.10 Pg.5 placed iron over stone found

12-1962 county highway department found rod over limestone. Set CIM over stone

8-27-1969 J. Kerr found CIM set by county highway department down 14" deep. Set short CIM flush with road surface.

11-18-1999 County Surveyor found CIM down 3" in blacktop CR 25 in good condition.

6-5-2001 County Surveyor found CIM down 0.3' in good condition. Set 1" square pipe w/cap as ref pipe. Tied out corner and removed CIM.

9-7-2001 County Surveyor set 1" square pipe w/cap at surface from 2001 overlay tie out.

4-18-2006 County Surveyor found 1" square pipe w/cap at surface in good condition.