Certificate of Location of Government Corner

ID#: 651805 **Description:** W SEC COR 18 19 65 **Date Set:** 7/22/2010 **County:** Olmsted

Section: 18 **Township:** 106N **Range:** 15W **Monument Description:** Cast iron cap on 5' telspar pipe

Reference Ties:

The cast iron cap is down 0.4'
The corner falls 2' north of centerline CSAH 25 west, 15' west of centerline CSAH 25 north and in centerline of Grandview Lane southwest.

Corner History:

10-1884 T. Hunter Pg.393-4 found stone in center of road

5-1893 W. Fraser Pg.508 No.477 found stone per Hunter survey Pg.394

11-1903 C. Armstrong Bk.B Pg.11 corner marked on plat

9-20-1970 Olmsted County Surveyor dug and found wood hub and small pieces of lath standing about where stone corner should have been. However, stone probably taken out with grading of road and ditches. Unable to find out who placed wood hub and lath, but it checks very good with measurements from North and East.

11-10-1970 Olmsted County Surveyor set 3/8" iron rod at location of wood hub found.

12-5-1977 Zenk Engineering set 1/2" pipe w/cap as corner for survey in NW 1/4 section 19.

6-14-1991 Vince Fangman found and used 1/2" pipe as corner for survey in NW 1/4 section 19.

3-1-1994 Vince Fangman shows found CIM on plat of Grand View Subdivision in NW 1/4 section 19.

Note: (Olmsted County has no record of CIM being set at this corner.)

9-15-1995 Vince Fangman found and used 1/2" pipe as corner for survey in SW 1/4 section 18.

12-21-1995 Vince Fangman found and used 1/2" pipe as corner for survey in SW 1/4 section 18.

2-2-2010 Olmsted County survey crew found 1/2" pipe down 0.1', leaning. Removed pipe and took measurements to nearby survey monuments to compute a replacement position.

7-22-2010 Olmsted County Surveyor computed a position based on survey monuments found in Grand View Subdivision and Vince Fangman and Zenk Engineering certificates of survey. County survey crew set a cast iron cap on telspar pipe at the computed position.