Certificate of Location of Government Corner

ID#: 651904 **Description:** 1/4 SEC COR 19 30 65 **Date Set:** 4/19/2002 **County:** Olmsted

Section: 19 **Township:** 106N **Range:** 15W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 5' north of centerline of abandoned road
PK nail in 8" Cedar CP NNW 17.02'
Pepsi cap in S side PP #95 WNW 71.41'
Post w/sign 2' north
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes: Michael Karrick, Deputy Surveyor N89°57'E on true line between sections 19 and 30. 39.73 chs. Set quarter section post. Burr Oak 12 in. N18°E 345 lks. Burr Oak 9 in. S75½°E 256 lks. 79.73 chs. Section corner.

8-1857 E.P. Bircher, Surveyor per J.B. Fellows, Deputy (Old Road Book Old Road 78) survey the road between section 19 and 30 and makes a call for this corner (no description).

5-1894 William Fraser, County Surveyor, (Book B, Page 92) measured from 1/4 cor. 24-25, T106N, East to Sec. Cor. 19-20-29-30 to set W. Sec. Cor. 19-30 but apparently did not find 1/4 Cor. 19-30 and does not mention setting it.
He staked the E-W road between Section 19 and 30. His measure from 1/4 Cor. 24-25 to Sec. Cor. 19-20-29-30 Was recorded as 20 links short of Gov't measure.

11-1903 C. Armstrong (Book B, Page 68) "ran line West from the S.E. Cor. 19 Found a stone at the 1/16 West at 19.97 chs. and on line, found 1/4 Cor. 19-30 (shows 12x10x12 stone on plat) at 39.88 chs. and on line, and found a stake at the 1/16 West of 1/4 Cor. 19-30 at 59.84 chs. And on line." Measured 79.50½ chs. to S.W. 19 He used this corner to set the 1/16 North, a stake, midway (19.91 chs.) and on line to the Center 19, a stake found.

1929 John Kerr, County Surveyor, (Kerr Book 1, Page 10-12) measured from a stake found at the N. 1/4 Cor.19 52.43.3 South to a stone found at 1/4 Cor. 19-30. He used these corners to set the center 19.

9-1970 County Surveyor inquired at farm of George Evjen who said stone was in. Found abandoned road in 3' cut made years ago. Found stone in North track, 8"x12"x16" lying upright but not in longest way. Set a C.I.M. Over a 1/2"x30" pipe with the stone on the North side.

9-29-1981 County Surveyor found the C.I.M. broken and the stone exposed in deep wheel rut in old road. Removed C.I.M. and stone. Drove pipe found beneath the C.I.M. deep and set a new C.I.M. over it. Reset stone on South side of the C.I.M. Set a survey marker sign and post 3½' North of the C.I.M. The corner is 5' North of the center of the old road.

4-18-2002 County Surveyor found CIM down 2.6' in good condition.

4-19-2002 County Surveyor set a CIM over existing CIM at surface. Set sign and post 2' North.