Certificate of Location of Government Corner

ID#: 651905 **Description:** W SEC COR 19 30 65 **Date Set:** 7/25/2003 **County:** Olmsted

Section: 19 **Township:** 106N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

County Survey Disk in SW side PP SE 70.54'
County Survey Disk in SE side driveway entrance post NE 32.84'
Pk nail in concrete CP NE 38.4'
Punch mark in E end 36" CMP SSE 65.66'
Punch mark in W end 36" CMP WSW 64.11'
This corner is located by GPS measurement

Corner History:

10-1853 John Ball, 80.00 set post and drove charred stake corner to sec's 19, 24, 25 & 30. Built mound with trench per instructions. Planted SE Osage Orange NE Apple seed.

9-17-1947 J.Kerr (Dodge-Fillmore Book P.58), found stone after extensive deep digging set 1-1/4" pipe in place of stake South of stone. New bearing to corner Burr Oak S 67° E 58.2'. Shows meas South to W 1/4 30 2632.7.

9-22-1970 Olmsted County Surveyor found pipe at road surface battered on top by machinery pulled pipe out and set 38" pipe in its place below CIM and glass.

4-18-2002 Olmsted County Surveyor found 5/8" iron rod down 0.1' in good condition.

4-22-2002 Olmsted County Surveyor found 5/8" iron rod, removed. Found CIM down 3.6'. Set 1/2" iron rod down 0.2' over existing CIM. Rod to be replaced.

7-25-2003 Olmsted County Surveyor found 1/2 iron rod down 0.2', removed and found CIM down 3.6'. Took local ties and removed. Set 6' telspar pipe w/CIC down 0.5' from local ties. CSD with concrete nail in SW side of PP (no #) 70.54' SE. CSD w/concrete nail in SE side of easterly 18" old PP now used for driveway entrance posts 32.84' NE.

2-1-2010 Olmsted County Surveyor found cast iron cap on telspar pipe down 0.5' in good condition.