Certificate of Location of Government Corner

ID#: 651906 **Description:** W 1/4 SEC COR 19 65 **Date Set:** 2/4/2010 **County:** Olmsted

Section: 19 **Township:** 106N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls at fence corner west and south, corner post is decayed and down
Post w/sign 2' NE
County Survey Disc with nail in east side of 36" maple is South, 6.39'
County Survey Disc with nail in south side 8" elm is East, 23.18'
This corner is located by GPS reference stations "Party A & B"

Corner History:

10-1853 John Ball 40.00 set post for quarter section corner. Black Oak 10 N 30 E 36 links. Burr Oak 18 N 66 W 39 links. 41.00 top of bluff, course SE. 44.20 brook 12 links wide runs 51.50 brook 15 links wide runs SW.

5-30-1894 W.Fraser (P.92B) found stumps of NW & NE bearing trees located corner and set stone as corner. Meas South on mile setting SW 19 midway 39.87-1/2 2631.75.

11-1903 C.Armstrong (P.68B) found sandstone 6" x 10" pointed on top 10 above ground tested by stump of NW bearing tree. New bearing tree Black Oak 12" S 39° 30' E 17.82 27 links marked tree. 1/16 South stone 6 x 12 x 16 M&L 19.91 (1314.0). South set stakes at 3.32 219.1. Then 662.2- 437.0 then 9.944 (656.3) to above 1/16. Ran line E to D or SE 19 North to W 1/4 19 39.82 (2628.12.) Set stones at "1" a 1/16 19.91 (1314.06) then set stone at "4" a prop corner at 9.955 (657.03) then set stone at "5" a prop corner at 6.633 (437.78) then found W 1/4 19 stone 6" x 10" up 10" at 3.322 (219.25) rough wooded line must cross river somewhere.

12-5-1977 Zenk Engineering Inc. found corner and used it in NW 1/4 sec 19 survey.

4-1-1985 Vince Fangman found and used 5/8" iron pipe as corner for survey in sec 19, 106-15 and sec 24, 106-16.

8-6-2003 Olmsted County survey crew set 5' telspar pipe w/CIC over 5/8" pipe. Monument falls in line with old remnants of N-S fence. Set post 2.0' East of monument.

2-4-2010 Olmsted County survey crew discovered that the telspar pipe placed on August 6, 2003 had been incorrectly set over a 5/8" pipe 218.86' south of the west quarter of Section 19 at the southwest corner of Outlot A, GRAND VIEW SUBDIVISION. County survey crew removed the telspar pipe and set it over a 5/8" pipe at the west quarter of Section 19.