Certificate of Location of Government Corner

ID#: 652109 **Description:** SEC CEN 21 65 **Date Set:** 6/16/1972 **County:** Olmsted

Section: 21 **Township:** 106N **Range:** 15W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
1" rod

Reference Ties:

The 1" rod is down 1.2'
The corner falls 3' north of centerline of E-W twp road and 1' west of centerline twp road south
East nail on No. plate PP #9124 SE 60.35'
20d nail in E side 18" Oak up 5' N 43.15'
Large boulder setting up (meas. Taken at the top crack) SW 76.25'
This corner is located by GPS measurement

Corner History:

1-1891 T. Fraser Bk. A pg.449 Found the stake and the stone claimed set by T. Hunter.

3-24-1895 W. Fraser Bk. A pg.618 found the corner stone on the E-W quarter line but 26lks. (17.16') west of the N-S 1/4 line. Moved the corner and set a 3"x8"x24" stone and stake at the true 1/4 lines intersect. Set 1/16th corner stone east, west, south and the 1/64th stone to the north.

6-16-1972 County Surveyor found the limestone as the corner, the 1/16th E., the 1/16th south, and the 1/64th corner stone north. Set 1" x 4' rod over stone.

9-1-1976 McGhie & Betts found and used 1" iron shaft for Salem Heights First Subdivision.

6-9-1977 K. Ewers found and used 1" shaft.

4-28-1992 County Surveyor found and used 1" iron set in 1972 in good shape. 1/16th S of center 21 stone found and iron set in 1972 are now gone in road construction.

8-4-1994 V. Fangman found and used 1" iron shaft at center of section 21.

12-14-1995 V. Fangman found and used 1" shaft at center of section.

8-4-2008 V. Fangman used computed location at intersecting quarter lines as center of section 21.

2-18-2010 County survey crew found 1" rod down 1.2' in good condition