Certificate of Location of Government Corner

ID#: 652309 **Description:** SEC CEN 23 65 **Date Set:** 10/24/1973 **County:** Olmsted

Section: 23 **Township:** 106N **Range:** 15W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
1/2" pipe

Reference Ties:

The corner falls 4' north of E-W fence and 14' west of N-S fence
County Survey Disk in S side 18" Oak ENE 17.33'
Post w/sign 2' north
This corner is located by GPS reference stations "Pisces B & C"

Corner History:

6-3-1874 T. Hunter (P.254 No.254) set stake true inters lines. 3" Jack Oak S 50° W 1-1/2 lks no other trees near. 1/16 East set stake 20.09-1/2 M&L N 89° 17' E line South. 1/16 West set stake 20.01 M&L N 89° 17' E line South. 6" Burr Oak N 81° E 52-1/2 lks 6" Burr Oak S 4-1/2° E 108 lks. 1/16 North set stake 20.00 M&L S 10° E line West. 1/16 South set temp stake M&L 19.94 line West. 1/16 center SW 1/4 23 set stake M&L 19.94 E-W 1/16 line.

12-17-1894 W.Fraser (P.562 No.516) drove stake and set stone at true inters lines. 1/16 West set stone and stake M&L 20.01 to stone 6" Burr Oak S 3° E 111 lks (found 6-21-72 stone and tree both). 1/16 East set stake M&L 20.02-1/2 to limestone. 1/16 South set stone and stake M&L. 1/16 center SW 1/4 23 set stone M&L 19.94-1/2 N-S 1/16 line. 1/16 North set stake M&L 19.97 M&L corner fence post.

6-21-1972 County Surveyor found 1/4 22-23 and 1/16 stone East meas 1/16 West to 1/4 22-23 without line 1320.66± R1320.66. Investigated line East to center 23 meas roughtly on offset North land very rough with center 23 area in steep wooded area showing erosion. Nothing gained in future search as stones all over. Line and elect meas on 50 foot or more offset (East 1/2) likely less (West 1/2) North would easily handle line and likely locate stone (being a W.Fraser corner).

9-27-1973 County Surveyor found traverse points set in Tom Taylor survey which should place stone if in place 13 ±' South and little West (see field notes) there was a short thick limestone pointed coming to surface in near exact spot so set 12" of bottom of tee shaped corner post with limestone on N side and another piece of limestone on N side. 4' S to E-W fence 14' ± E to N-S fence.

10-24-1973 County Surveyor, after setting 1/4 14-23 reset center 23, removed stone and iron tee post part set 1/2" x 18" pipe as corner .52' due West no stones by or below iron pipe. Left pipe up 2" change in RP's over a small 1" tree former 5.1 RP now 5.2' due S.

5-11-1992 V. Fangman used computed center.

12-22-1992 Roger Brand found and used 1/2" pipe at center of section.

6-18-2002 GGG found and used monument at center of section.

10-19-2006 County Surveyor found 1/2" pipe up 0.1' in good condition. CSD with concrete nail in south side of 18" oak 17.33'.