Certificate of Location of Government Corner

ID#: 652405 **Description:** SEC COR 23 24 25 26 65 **Date Set:** 10/13/2006 **County:** Olmsted

Section: 24 **Township:** 106N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 6' north of centerline of E-W twp road
Conc. nail in NE side PP #7812 SSE 39.55'
20d nail in SE side 24" Oak NE 109.5'
County Survey Disk in SE side 18" Ash NNE 37.03'
This corner is located by GPS measurement

Corner History:

6-1854 Michael Karrick 80.00 set post for corner to sections 23,24,25 and 26. Burr Oak 12 S 58 E 207. Dug trench.

5-1873 T. Hunter, corner gone, reset stake center road by witness tree.

6-1874 T. Hunter (Book A P.254), found the stake set in a previous survey.

4-1898 W. Fraser (Book A P.624) Corner lost and gone, reset it with a 2"x9"x18" stone and also the 1/16th corner North.

8-1959 McGhie dug for corner found nothing. 18" deep in line fence running North. Set rod in line fence North 3' ± North of center road. Meas East to stone found 2636. (Removed this rod).

Note: This correct corner was 2.1' North and 1.22' East of the assumed iron pin used in previous surveys.

6-23-1972 County Surveyor found the recorded limestone and wood stake and set CIM with a 1/2"x30" rod over stone and stake.

10-13-2006 County Surveyor found CIM with head broken off down 1.2' in good condition. Took local ties and removed. Found stone with 1/2" rerod on west side down 3' in good condition. Removed stone and set 4' telspar pipe w/cast iron cap down 0.4' at CIM position.