Certificate of Location of Government Corner

ID#: 652504 **Description:** 1/4 SEC COR 25 36 65 **Date Set:** 8/13/1980 **County:** Olmsted

Section: 25 **Township:** 106N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1' east of fence north and 1' south of fence east
Spike in W side CP NW 1.71'
Sign on CP 1 1/2' NW
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes Michael Karrick, Deputy Surveyor West on true line between sections 25 and 36. 40.00 chs. Set quarter section post. Burr Oak S25°W 491 links dug trench.

5-6&7-1873 Thomas Hunter, County Surveyor, (Book A, Page 220, No. 224 and Old Fieldbook 3, Page 10) "found remains of mound in fence and pieces of rotten stake in the center below the surface." He used this corner to set temporary stake at the 1/16 East (20.01 chs.) a permanent state at the 1/16 West (20.01½ chs.) and stake at the 1/16 South the Center 36, and the 1/16 South of the Center 36.

5-8-1873 T. Hunter (Book S, Page 222, No.225 and Old Fieldbook 3, Page 11) found stake in mound as described in Survey No. 224. He used this corner to set stakes at the 1/16 North, the Center 25, and the 1/16 North of Center 25.

9-9-1969 John Kerr, County Surveyor, set a long twisted 1/2" rod at the base of rotted leaning corner post in exact line of fence North. Measured 1320.5 East to the 1/16 fence and 2641.0 to the fence South at the East Sec. Cor. 25-36.

8-13-1980 County Surveyor dug a small hole on the South side of the corner post to fence North and East. Found soft spot which was the probable location of an old post. Drove a 4' telspar with a Cast Iron Cap at this location as the corner. Measured 2639.86 to Kerr's pipe set in line of the main line of fence West, East, and South at East Sec. Cor. 25-36 and 2640.16 West to Sec. Cor. 25-26-35-36 set this survey.

10-5-2006 County Surveyor found cast iron cap on telspar pipe at surface in good condition.