Certificate of Location of Government Corner

ID#: 652604 **Description:** 1/4 SEC COR 26 35 65 **Date Set:** 8/13/1980 **County:** Olmsted

Section: 26 **Township:** 106N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 2 1/2' south of fence east and 2 1/2' east of fence south
Spike in S side 8" Elm E 69.28'
Spike (up 4½') in W side 15" Burr Oak SW 65.20'
Sign on CP 1' SW
This corner is located by GPS reference stations "King C & D"

Corner History:

1854 Michael Karrick, Deputy Surveyor West on line between sections 26 and 35. 40.00 chs. Set quarter section post. No trees of sufficient size for bearing therefore erected mound with, trench, pitts, charred stake, and Osage orange seeds N.E. & S.W. 80.00 chs. Section corner.

2-1877 Thomas Hunter, County Surveyor, (Old Field Book 4, Page 172) "found mound with pole in center where 1/4 post stood".

12-1884 Thomas Hunter (Old Field Book 14, Page 28) apparently used this corner to stake wood lots on the N-S 1/4 line of Section 35 (he used a stake found at the Center 35.)

6-1887 Thomas Hunter (Book A, Page 420, No. 409 and Old Field Book 14, Page 83) "1/4 post missing and no trace of it could be found by careful search and digging and no evidence of where it stood." He set a stake driven well down midway and on line between the section corner. He used this corner to set the 1/16 West, the 1/16th North and a stone at the Center 26.

11-10-1970 County Surveyor dug for this corner but did not find anything. Set a 3/8" rod midway and on line from Sec. Cor. 26-27-34-35 to a point in the center of the road and in line with the fences East and West at Sec. Cor. 25-26-35-36.

7-3-1980 &
8-6-1980 County Surveyor dug again but did not find anything.

7-29-1980 County Surveyor dug at the 1/16th West but did not find anything.

8-13-1980 County Surveyor set a 6' piece of telespar with a Cast Iron Cap as the corner at the intersection of the line from the N. 1/4 Cor, 26 (reset 1973) over the Center 26 (found 1970) and the line from Sec. Cor. 26-27-34-35 (found 1970) to Sec. Cor. 25-26-35-36 (set this survey).

10-10-2006 County Surveyor found cast iron cap on telspar pipe down 0.1' in good condition.