Certificate of Location of Government Corner

ID#: 653006 **Description:** W 1/4 SEC COR 30 65 **Date Set:** 3/18/2009 **County:** Olmsted

Section: 30 **Township:** 106N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in centerline of N-S twp road
This corner is located by GPS measurement

Corner History:

10-1854 John Ball, 15.02 Black Oak 15" in diameter, 40.00 set post for quarter section corner. Burr Oak 16 S 45º E 191 links. Burr Oak 12 N 81º E 244 links.

5-1894 W. Fraser Pg. 92 B found stone planted as corner.

9-1970 Olmsted County Surveyor found large solid steel shaft as corner. No Dodge County Surveyor or any local surveyor knew of this corner. Will dig in area with tractor, land line no chance stone gone.

9-30-1970 Olmsted County Surveyor, shaft proved to be short cast sash weight. Dug with tractor found below sash weight with limestone 5 x 8 x 32 in clean black soil. Stone to long to bury, broke in half, placed 1/2 on N side 1/2 on S side also slim stone sliver 3 x 7 x 18 ± on E side. Set full length modet T axle below CIM glass etc. Corner lines fence East and old fence in massive tree line W. 40d in hub on N side of Easterly of turn massive oaks near 24". This tree have siamese limb connecting them about 8' up E & W very unique growth 5' N of W 88.5. Coke cap on SW side PP #3803 SE 54.4. Hard nail on S side new 8" cress corner post E 33.02. Corner in center road in line fence East.

11-15-1985 Olmsted County Surveyor, L.C. says CIM gone. Set 1/2" x 12" pipe .2 below surface in centerline using ties. Tie to CP East also gone.

9-18-2001 GGG, Inc. found and used pipe as corner for survey in NW 1/4 section 30-106-15.

10-26-2001 V. Fangman found and used 1/2" pipe as corner for survey in SW 1/4 section 30-106-15.

3-18-2009 Olmsted County Surveyor found 1/2" pipe down 0.3' in good condition. Took ties and removed. Set a 5' telspar pipe w/Cast Iron Cap down 0.5' at pipe location.

2-2-2010 Olmsted County Surveyor found cast iron cap on telspar pipe down 0.4' in good condition.