Certificate of Location of Government Corner

ID#: 653506 **Description:** 1/4 SEC COR 34 35 65 **Date Set:** 6/30/1972 **County:** Olmsted

Section: 35 **Township:** 106N **Range:** 15W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 7' east of centerline of N-S twp road
Top rivet E end 15" CMP SE 44.01'
Punched hole in N end 18" CMP ENE 19.84'
Concrete nail in small knot on E side PP #7479 up 2' SSW 98.93'
This corner is located by GPS measurement

Corner History:

6-1854 Michael Karrick 40.00 set quarter section post. White Oak 12 N 47 W 5.00. Black Oak 12 N 43 E 3.08.

3-20-1889 Thos. Fraser unrecorded survey in small field book marked xxx found stake as 1/4 corner 8-2/3 lks (5.72') East of direct line between 1/16 stake North of 1/4 corner and section corner S 34-35 Salem a stone no meas of any kind onthis line.

6-1932 J. Kerr (B.8 P.14) meas from NE 34 South to fence running East 2637.5 to determine mean N-S meas on 1/16 line of NW 1/4 34.

10-26-1970 County Surveyor dug with tractor for 1/16 corner found limestone with large stake on S side, accepted stake as corner. Set 1" x 3' ± galv pipe as corner.

10-26-1970 County Surveyor dug from 2' E of centerline East over 5' found where extensive search had been made for corner very near entire area. If stake in place was likely destroyed, dug 5' deep very wet, heavy rain during operation, real mess. Set 1/2"x3' long iron.

6-30-1972 County Surveyor found rod. Set CIM by RP's to culvert, placed 1/2"x2' rod below CIM.

1-14-1992 Vince Fangman took RP's top rivit on E end 15" CMP SE 44.01' (CMP running E-W across twp rd). Punched hole on N end 18" CMP under field drive ENE 19.84'. PK in same place as concrete nail in small knot in PP #7479 SW 98.93'.

10-4-2006 County Surveyor found CIM down 1' in good condition.