Certificate of Location of Government Corner

ID#: 653605 **Description:** S SEC COR 35 36 65 **Date Set:** 10/24/1996 **County:** Olmsted

Section: 36 **Township:** 106N **Range:** 15W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 5' south of centerline of CR 126 west, 6 1/2' south of centerline of twp road east and 3' east of centerline of CSAH 15
County Survey Disk in PP ESE 97.33'
Punch + in S end 30" CMP SW 40.48'
Punch + in N end 30" CMP NW 43.89'
County Survey Disk in PP #7326 NW 59.70'
Ref. pipe WSW 102.23'
This corner is located by GPS measurement

Corner History:

1853 Gov't notes John Ball, Deputy Surveyor West between section 1 and 36. 80.00 chs. Set post and drove charred stake corner to Sections 1, 2, 35 and 36. Built mound with trench per instructions. Planted S.E. Osage orange N.E. Apple seed.

3-1858 G. Marcwell, Surveyor (Old Road Book-- Road No. 96) surveyed a road between Section 1 and 2 and 35 and 36. Measured south 39.48 chs. (2605.68) to 1/4 Cor. 1-2 and 80.00 chs. North to Sec. Cor. 25-26-35-36.

5-6&7-1873 Thomas Hunter, County Surveyor, (Book A, Page 220-221, No. 224 and Old Field Book 3, Page 10) "Found stake in the center of the road claimed to be where original corner stood." He used this corner to set temporary staked at the 1/16 North and 1/16 East.

1959 County Highway Department (C.H.D. Books 241 and 242) assumed corner at the center of the intersection of roads N-S-E-W. Set 16d spike.

11-1969 John Kerr, found large nail in center of blacktop slightly South of the centerline of roads East and West.

11-1969 John Kerr, found large nail in center of blacktop slightly South of the centerline of roads East and West.

10-31-1978 County Surveyor dug for this corner but found nothing.

7-3-1980 County Surveyor dug for the 1/16 Est but found nothing.

8-13-1980 County Surveyor set a C.I.M. over a 1/2" x 18" iron as this corner at Hunter's measure from the S. 1/4 cor. 36 and at hunter's prorated measure from Sec. Cor. 25-26-35-36 (prorated against our measure from Sec. Cor. 25-26-35-36, a distance measured by Hunter in 1873 at the same time he measured the West line Section 36.

6-27-1996 County Surveyor found CIM 4" deep in C.R. #15, set 1" sq ref. Pipe w/cap on South shoulder C.R. #126 West of C.R. #15 South of centerline C.R. #126. Angle at Ref. Pipe. Angle RT PK in PP #24906 2nd pole West of C.R. #15 on South side C.R. #126 to South sec cor 35-36. 180 50' 50" to sec cor Hor 102.23. Removed CIM 6-27-1996.

10-24-1996 county highway department set 1" sq. pipe w/cap

11-1-2002 County Surveyor found 1" square pipe w/cap at surface in good condition.

3-20-2006 County Surveyor found 1" square pipe w/cap at surface in good condition.