Certificate of Location of Government Corner

ID#: 653606 **Description:** 1/4 SEC COR 35 36 65 **Date Set:** 10/24/1996 **County:** Olmsted

Section: 36 **Township:** 106N **Range:** 15W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 1 1/2' south of fences east and west and 1 1/2' east of centerline of CSAH 15
County Survey Disk in PP #7313 W 49.75'
Ref pipe SSE 98.14'
This corner is located by GPS measurement

Corner History:

6-1854 Gov't Notes Michael Karrick, Deputy Surveyor North between section 35 and 36. 40.00 chs. Set quarter section post. Black Oak 10 in. S80°E 6 links.

3-1858 G. Marcwell, Surveyor, (Old Road Book--Road No. 96) surveyed the road between Section 35 and 36 but did not mention this corner.

5-6&7-1873 Thomas Hunter, County Surveyor, (Book A, Page 220, No. 224 and Old Field Book 3, Page 10) "Found stake in center of road claimed by Mr. Nelson and others to be where original corner stood." Set a stone 2"x9"x20" in its place. He used this corner to set temporary stakes at the 1/16 North and 1/16 South, and stakes at the 1/16th East, the Center 36, and the 1/16 East of the Center 36. Hunter's field book shows this corner was 4½ lks. West of a straight line between the section corners.

1959 County Highway Department (C.H.D. Books 241-242) ran Co. Rd. 15 alignment straight from an assumed corner a S. Sec. Cor. 35-36 to an assumed corner at Sec. Cor. 25-26-35-36 and makes no mention of this corner.

7-7&9-1980 County Surveyor dug for this corner but did not find anything.

8-13-1980 County Surveyor set this corner 4½ lks. West of a straight line between the section corner and at Hunter's prorated measure from Sec. Cor. 25-26-35-36 (prorated against our measure) from 1/4 Cor. 25-26 to Sec. Cor. 25-26-35-36, a distance measured by Hunter in 1873 at the same time he mearsured the West line Section 36.

8-3-1995 County Surveyor found CIM 10" deep in blacktop C.R. #15.

6-27-1996 County Surveyor found CIM 9" deep in C.R. #15. Set Ref. pipe on ditch slope SSE of corner 21-1/2' East of centerline. Angle at Ref. pipe, angle RT PK in PP #D15-35-10.0 to 1/4 cor 152° 32' 06" to 1/4 cor 98.14. county highway department disk in PP #D15-35-11.0 WNW 49.70.

10-24-1996 county highway department set 1" sq. pipe w/cap.

4-21-2006 County Surveyor found 1" square pipe with cap at surface in good condition.