Certificate of Location of Government Corner

ID#: 710205 **Description:** SEC COR 2 3 10 11 71 **Date Set:** 4/13/2010 **County:** Olmsted

Section: 02 **Township:** 107N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is flush with the surface.
The corner falls 10' east of deep gully
Post with sign 0.8' east
This corner is located by GPS reference stations "Gully Road A & B"

Corner History:

10-1853 Gov't Notes William A. Jones, Deputy Surveyor North between sections 10 and 11 75.00 chs To foot of bluff 100 ft. 79.00 chs Perpendicular rock 30 ft. 80.00 chs Set section post corner to sections 2,3,10,&11 from whence a Black Oak 10 in. diam. N25°W 95 lks. An Elm 8 in. diam. S48°E 45 lks. An Elm 7 in. diam. S55°W 06 lks with a pile of rock round post.

1857 Road Survey (E.P. Bircher, Surveyor), used the corner in the survey of the road.

10&11-1900 William Fraser (P. 692-8 No. 615 and Old Field Book 9 P.61-67) County Surveyor, found a red cedar stake in the center of a pile of rocks. The corner was 25 lks. East of the road. Took a bearing tree: 8" Slippery Elm S62°W 7 lks.

8-1928 John Kerr (B-1 P.19-22), County Surveyor, found the red cedar stake and the bearing tree taken by Fraser.

1933 County Highway Department (B.73 P.73) found a red cedar stake just East of a 15 in. Basswood tree.

6-20-1977 County Surveyor found a cedar stake standing 4 1/2' East of an 18" Basswood believed to be the bearing tree taken by Fraser. The stake was 32" long with 12" above ground. Removed the stake to the office and drove a Cast Iron Cap on a square pipe in the stake hole. Drove a steel fence post 2' West of the corner.

1-6-2009 County survey crew found cast iron cap on telspar pipe up 1' leaning North.

4-13-2010 County survey crew found cast iron cap with sq. pipe leaning west, removed. Set 2' telspar pipe with cast iron cap flush with surface using previously measured coordinates.