Certificate of Location of Government Corner

ID#: 710206 **Description:** 1/4 SEC COR 2 3 71 **Date Set:** 6/24/1977 **County:** Olmsted

Section: 02 **Township:** 107N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 16' west of edge of Whitewater river
Spike in W side blazed 9" Box Elder N 20.48'
Spike in SW side 28" Blazed Cottonwood NW 67.80'
Spike in S side blazed 7" Box Elder NW 5.05'
Spike in E side blazed 9" Box Elder SW 16.10'
Spike in E side blazed 9" Box Elder SSW 95.5'
Steel fence post on north side of monument

Corner History:

10-1853 Gov't Notes William A. Jones, Deputy Surveyor South on true line between sections 2 and 3. 35.50 chs. To foot of bluff and a stream 90 lks. wide course N & S on line and from thence East. 39.50 chs. Place for quarter section corner in stream. Established witness corner 47 lks. East of true corner from whence an Elm 18" diam. S30°E 47 lks. Linden 12 in. diam. N85°E 39 lks. 79.50 chs. To section corner.

10&11-1900 William Fraser (P. 692-8 No. 615), County Surveyor, states that the corner was gone for years. Set an iron stake 40" long with a bur at the bottom and marked stake by side on the line between the section corners and at prorated Gov't measure.

6-24-1977 County Surveyor found Fraser's 40" bolt with a 1 1/4" pipe over it. Removed the bolt and set a Cast Iron Cap on a square pipe as the corner. Set a steel fence post on the North side of the monument.

3-2-2010 County survey crew found cast iron cap on telspar pipe down 0.5' in good condition.