Certificate of Location of Government Corner

ID#: 710305 **Description:** SEC COR 3 4 9 10 71 **Date Set:** 10/3/1977 **County:** Olmsted

Section: 03 **Township:** 107N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 37' north of rough fence east
County Survey Disk in S side blazed 9" Burr Oak N86°W 34.75'
County Survey Disk in E side blazed 11" Black Oak N2°W 31.43'
County Survey Disk in E side 12" Burr Oak S14°W 25.40'
Spike in W side 14" Burr Oak used as CP S 38.69'
Telspar pipe (up 3') 1 1/2' north
This corner is located by GPS reference stations "Bones C & D"

Corner History:

10-1853 Gov't Notes William A. Jones, Deputy Surveyor North between sections 9 and 10. 80.00 chs. Set section corner post to sections 3,4,9,10. Bur Oak 6 in. diam. N10°W 95 lks. Bur Oak 8 in. diam. N15°E 124 lks. Bur Oak 8 in. diam. S7 1/2°E 81 lks. Bur Oak 12 in. diam. S45°W 5 lks.

10-1893 William Fraser (P. 538 No. 499), County Surveyor, found mound and pits. Planted a stone in the center of the mound.

10&11-1900 William Fraser (P. 692-8 No. 615 and Field Book 9 P. 68-79 and p. 81-82), County Surveyor, found the remains of the old Gov't stake and the stumps of 3 of the Gov't bearing trees which corresponded with the stake as found. Set a 8" x 8" x 24" stone running to a point on top with other stones laid around it and took two new bearing trees both of which had grown out of the stumps of the old Gov't bearing trees: 8" Bur Oak S50°W 6 lks. and 8" Bur Oak N10°W 76 lks. The corner set Page 538 stood 46 lks. South and 6 lks. East of the correct corner. Set the S. 1/4 Cor. Sec. 3 midway and on line between the section corners.

7-1933 County Highway Department (B. 73 P. 73) found a red cedar stake in a mound of rock.

9-14-1977 County Surveyor found a ring of stones on the North side of the base of the old corner post (post laying down). Dug out the stones to search for Fraser's 8" x 8" x 24" stone. Found nothing further; however, one of the stones there was 8" x 8" x 16" and is possibly Fraser's stone dug out and broken when the corner post was set. A rotted stump stands 4' SW of the base of the corner post and could possibly be Fraser's bearing tree which would place the corner at the post.

10-3-1977 County Surveyor set a Cast Iron Cap on a square pipe as the corner on the line and at double the measure from the SE Cor. Sec. 3 over the S 1/4 Cor. 3. The corner came at the location of the old post. Set a square pipe (up 3') on the North side of the monument.

12-4-2008 County Surveyor found cast iron cap on telspar pipe up 0.3' in good condition.