Certificate of Location of Government Corner

ID#: 710606 **Description:** W 1/4 SEC COR 6 71 **Date Set:** 10/17/2011 **County:** Olmsted

Section: 06 **Township:** 107N **Range:** 11W **Monument Description:** Cast iron cap on telspar pipe

Reference Ties:

The monument is down 0.5'
The corner falls in centerline of N-S twp road and in line with cemetery fence east
PK Nail in NE side PP #38248 NW 41.11'
Punch Cross in NW side 6" steel gate post SW 54.65'
This corner is located by GPS measurement

Corner History:

1853 Gov't. Notes John Ball, Deputy Surveyor North between section 1 and 6. 40.00 chs. Set quarter post. Burr Oak 10 in. N71/2ºW 470 lks. Dug trench.

6-1902 Robert Fraser (unrecorded survey-field book #10 P. 42), County Surveyor, found a stone coming to a point in line with fence running east in center of road.

8-16-1972 County Surveyor dug area with Wharton D7 cat and found 8"x10"x13" boulder in center of road and in approximate line with cemetery fence east. Set a 1/2" x 31/2" iron pipe on south side of stone.

6-11-1974 County Surveyor set C.I.M. over stone found in 1972.

12-15-2005 County Surveyor found CIM w/head broken off down 0.5' in good condition.

10-17-2011 County survey crew found CIM with head broken. Removed and found 8"x10"x13" stone directly below. Removed and replaced with a 6' telspar pipe with cast iron cap.