Certificate of Location of Government Corner

ID#: 710806 **Description:** 1/4 SEC COR 7 8 71 **Date Set:** 9/4/1990 **County:** Olmsted

Section: 08 **Township:** 107N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls south of CP of E-W fence
This corner is located by GPS measurement

Corner History:

9-1853 Gov't Notes. William A. Jones Deputy Surveyor North between sections 7 and 8. 40.00 chs. Set quarter section post in mound of earth and sod, deposited charcoal, made trench and pitts. Planted osage orange seeds east and west of trench.

6-1877 Thomas Hunter County Surveyor (Page 317, No. 311). Used corner post that Mr. William Leachout said he placed where original quarter post stood. Set 1/16 south stake and stone midway and online 19.92 chs., also 1/16 west stake and stone midway and online 19.94 chs.

11-1891 Thomas Fraser, County Surveyor (Page 460, No. 444) Found 12" of corner post used by Thomas Hunter in 1877. Set iron stake 1/16 north midway and online 19.94 chs. Mr. S. Jinks informed me his son set a 3' long stone in place of corner post, also set part of iron pump at 1/16 north in spring of 1892.

8-1-1990 County Surveyor dug at E-W fence and stub fence north, found an irregular 12" x 12" x 30" limestone lying flat on east side of corner post, found nothing else.

8-2-1990 County Surveyor, 1/16 North dug and found many pieces of iron, found pump 24" deep, found post mark 1 1/2' north of pump and old fence running north and east.

9-4-1990 County Surveyor dug on south side of corner post after finding pump at 1/16 north, found 3/4" x 54" iron shaft with gear on top. Set telspar pipe and C.I.C. at shaft location as this fits Thomas Fraser measure north.

12-20-2005 County Surveyor found telspar pipe w/CIC up 0.2' in good condition. Corner post lying flat, fence stub to the north gone.