Certificate of Location of Government Corner

ID#: 710905 **Description:** SEC COR 8 9 16 17 71 **Date Set:** 6/22/2011 **County:** Olmsted

Section: 09 **Township:** 107N **Range:** 11W **Monument Description:** Brass plug in concrete road

Reference Ties:

The corner falls in centerline crack of CSAH 10 and 4' east of field drive south.
The monument is at the surface.
This corner is located by GPS measurement

Corner History:

9-1853 Gov't Notes William A. Jones, Deputy Surveyor, set corner 80.00 chs. north of Section Corner 16-17-20-21 and dug trench. 20" Burr Oak S24W 420 lks.

11-1891 Thomas Fraser, County Surveyor, (P.459 No.443) found stake and stone set earlier by Thomas Hunter.

10-1900 William Fraser, County Surveyor, (P.692-8 No.615) found stone.

1928 John Kerr (B.1 P.19-22) found stone.

1933 county highway department (B.73 P.73) found old P.I. stake which was set from ties to stone. Found stone lying near fence running south. Reset stone from ties.

1945 county highway department had concrete block and nail at this corner (B.168 P. 23).

9-5-1974 County Surveyor dug with backhoe and found pieces of Co.H.D. cement block and drag tooth 3' deep with a very deep stake hole below. Accepted the stake hole as the corner location. Set 5/8" x 18" rerod in stake hole. Placed pieces of block around rerod and set CIM over all.

12-13-2006 County survey crew found CIM down 0.7' in good condition.

3-7-2007 County survey crew found CIM down 0.7' in good condition.

6-22-2011 Construction of CSAH 10 destroyed existing monument. County survey crew set a brass plug in concrete road using previous GPS coordinates.