Certificate of Location of Government Corner

ID#: 710906 **Description:** 1/4 SEC COR 8 9 71 **Date Set:** 10/30/1990 **County:** Olmsted

Section: 09 **Township:** 107N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

Witness corner 35.00' E on quarter line
This corner is located by GPS reference stations "Marshman and Witness Corner 710906"

Witness Corner: County Survey Disk in brace post W 8.86'
Post w/sign 1' east
This corner is located by GPS measurement

Corner History:

9-1853 Gov't Notes William A. Jones Deputy Surveyor North between sections 8 and 9 31.75 chs. A stream 10 lks. wide course NE 39.70 chs. Same stream 40.00 chs. In stream place corner. Established a witness corner 45 lks. west of true corner in mound of earth and sod, deposited charcoal made trench and pits planted osage orange seeds east and west of trench. 41.00 chs. Leave stream course NE.

10-1885 Thomas Hunter (Book 14, Page 54) Witness stake and mound gone, dug and searched, found old east-west fence. Old settlers avers fence was built on line when stake was standing. So took middle of creek on line of fence, measured east 12.5 chs. set a post, ran stake line south for fencing, parallel with west section line.

10-1893 William Fraser, Deputy Surveyor (Page 53B, No. 499) could not find corner.

6-1902 Robert Fraser (Book 10, Page 45) said corner was uncertain.

7-1933 county highway department (Book 73, Page 73) ran random line north from section corner 8, 9, 16, 17 found iron stake in ground near creek bank 2628.4'.

10-1990 County Surveyor found iron shaft on east ditch bank down 24", 22' south of east-west fence. This would be iron county highway department used, no records of who set it or how.

10-30-1990 County Surveyor. Set telspar pipe and CIC in bottom of ditch inline of main fence east-west as per Thomas Hunters avers of old settlers in 1885. Set witness corner telspar pipe and CIC 35.00' east on quarter line. Did not use iron shaft found as believed it to be a witness corner.

12-20-2005 Witness Corner: County Surveyor found telspar pipe w/CIC up 0.3' in good condition.