Certificate of Location of Government Corner

ID#: 711006 **Description:** 1/4 SEC COR 9 10 71 **Date Set:** 10/3/1977 **County:** Olmsted

Section: 10 **Township:** 107N **Range:** 11W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 12' north of E-W fence and 7' east of fence north
Post w/sign 13' south
This corner is located by GPS meausurement

Corner History:

10-1853 Gov't Notes William A. Jones, Deputy Surveyor North between sections 9 and 10. 40.00 chs. Set a quarter section post from whence a Bur Oak 6 in. N30°W --lks. Made a trench.

10-1893 William Fraser (P. 538 No. 449), County Surveyor, found a fence post hole where a Mr. Peter Fender claims the old corner stood. Placed a stone in the post hole and used it as the corner.

10 & 11-1900 William Fraser (P. 692-8 No. 615 and Field Book 9 P. 68-79), County Surveyor, states Peter Fender changes his avers and other parties wanted the corner claimed as lost so set a 4" x 5" x 20" stone midway and on line as the corner. Dug up the old corner.

8-1928 John Kerr (B.1 P. 22), County Surveyor, measured North from Sec. Cor. 9-10-15-16 and found 1/4 Cor. 9-10 and Sec. Cor. 3-4-9-10 "at proportionate distances".

1933 County Highway Department (B. 73 P. 73) found a 4" x 4" x 18" limestone with a red cedar stake on the North side.

9-1974 County Surveyor found the corner came in an old road or cattle lane eroded to about 2' deep. Found a 4" x 4" x 18" limestone lying on the ground which could be Fraser's stone eroded out and washed down hill. Also found a 3" x 12" limestone with pieces of limestone on the North and South sides approximately 8' SW'ly which could be the point at which the corner stood. Set a small angle iron to hold this location.

10-3-1977 County Surveyor set a CIM over a 1/2" x 2' rod as the corner 1.84' West and 1.23' South of the angle iron (removed) and midway and on line between the section corners as in Survey No. 615.

12-4-2008 County Surveyor found CIM down 0.4' in good condition. Set post w/sign.