Certificate of Location of Government Corner

ID#: 711105 **Description:** SEC COR 10 11 14 15 71 **Date Set:** 8/28/2002 **County:** Olmsted

Section: 10 **Township:** 107N **Range:** 11W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 1/2' south of centerline of CSAH 2 and 19 1/2' east of fence north
Punch hole in E end 18" CMP NW 41.0'
County highway disk in CP NW 53.92'
Punch hole in E end of 18" CMP SW 37.94'
County highway disk in CP SW 53.22'
Ref pipe SW 28.15'
This corner is located by GPS measurement

Corner History:

9-1853 Gov't. Notes, William A. Jones, Deputy Surveyor, set a post 80.00 chs. north of Section Corner 14-15-22-23 in mound of earth and sod, deposited charcoal, made trench and pits, and planted osage orange seed N.W. and S.E. of trench.

10-1900 William Fraser (P. 692 No. 615) County Surveyor, could not find corner. Set 4"x12"x24" stone with stake.

1928 John Kerr found corner and set 1/2"x2 1/2" iron by side.

5-1933 County Highway Department (B. 73 P. 2) found 4"x10"x24" limestone with 1/2" rod on north side.

11-1961 County Highway Department (B. 252) set C.I.M. over limestone with rod by side.

9-4-1974 Roger Brand, County Surveyor dug down with backhoe to prove corner location and found limestone with 1/2" rod and hub and pottery beside stone. Set 10" C.I.M. above the one in place to bring up to surface.

5-28-1992 County Surveyor found C.I.M. 4" deep in blacktop.

5-10-2002 County Surveyor set 1" square pipe w/cap as ref. For 2002 overlay. Tied out corner.

5-29-2002 County Surveyor removed CIM and found second CIM down 1.2'.

8-28-2002 County Surveyor set 1" square pipe w/cap over p.k. nail at surface.

12-12-2006 County Surveyor found 1" square pipe w/cap at surface in good condition.

3-6-2007 County Surveyor found 1" square pipe w/cap at surface in good condition.