Certificate of Location of Government Corner

ID#: 711404 **Description:** 1/4 SEC COR 14 23 71 **Date Set:** 12/5/1997 **County:** Olmsted

Section: 14 **Township:** 107N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1' east of old corner post and 1 1/2' east of newer CP
Post w/sign 1' north
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes Wm. A. Jones, set 1/4 sec post in mound of earth and sod deposited charcoal. Made trench and pitts, planted Osage Orange seed N and S of trench. Set 1/4 section corenr post M&L 40 chs 2640 corner farm lines E-W-S common N close to center high natural draw running very gently N Nly wide contours, not severe ravine etc.

T.H. field book 14 P.44 indicates by meas that 1/4 corner used at midway points, however no SE corner 14 was found either and meas goes to SE sec 13 so that this 1/4 corner is on a prorated position E-W over the two miles from SW 14 to SE 13 using Gov't meas prorated. This 1/4 corner position for N-S 1/4 line only.

12-5-1997 County Surveyor set cast iron cap on telspar pipe at midway point between section corners E&W, in line of fences east and west, which falls 1' east of old CP, which is lying down and 1-1/2' east of newer CP which anchors fence south. T. Hunter in 1885 found no corner. His old field book 14 shows position used at 39.91-1/4 chains E&W = 2634.22. We used our 1992 traverse points to set this corner. Set sign and post 1' north of corner with fiberglass fence post beside monument.

8-7-2009 County Surveyor found cast iron cap on telspar pipe up 0.5' in good condition.

3-9-2010 County Surveyor found cast iron cap on telspar pipe up 0.5' in good condition.