Certificate of Location of Government Corner

ID#: 711804 **Description:** 1/4 SEC COR 18 19 71 **Date Set:** 7/23/2003 **County:** Olmsted

Section: 18 **Township:** 107N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1' SW of CP for fences N-S-E
60d spike in 8" Burr Oak SE 8.0'
This corner is located by GPS reference stations

Corner History:

1853 Gov't Notes Wm. A. Jones, set 1/4 section corner post 40 chs west of 17-18-19-20 meas mile 80.12 5287.92 west 1/2 2647.92'. 10" Burr Oak S35W 213 links 140.6'. Corner entirely within one farm corner near high edge sharp slope sloping westerly to flat drainage area.

11-10-1875 T. Hunter (P.287 No.283) found stake standing properly marked as 1/4 post. Avered by M. G.H. Hamilton where the original 1/4 post stood witness trees grubbed out and gone. 16 S set stake marked 1/16 corner M&L 19.93 1318.4 to center 19 (a stake set true inters lines).

11-21to24-1892 Thos Fraser (P.500 No.471) corner "F" could find no trace of this 1/4 post spoken of by Hunter, dug entire area where the stake used to stand as corner had been gone for 3 years. Set stone 2x7x17 on line and midway between E&G. This he did not do according to gov't proportions shown on plat.

1945 county highway department (B.146 P.55) found flat limestone standing 1.2' NW of corner post of fences N-S-E.

4-2-1973 County Surveyor found large oak post in 24" ± dia concrete base in corner woods in level high lands. Stone likely removed in setting corner post. Old property fence N&S, commonly owned land all sides of corner. Set offset 285' south and ran east meas east on offset. Set nail at 1320' and found line 275 from old fence believed original line fence. No property sized stone eveident 4x8x14-1/2. Con't line east correcting to 285' and set nail in center road at random meas for 17-18-19-20 (see cards).

4-5-1973 County Surveyor reset 1/16 east from iron bolts north (see special card) following this card meas now from post in concreted in post. Final meas east to 17-18-19-20 = 2631.4 or 1315.85 then 1315.55 to sec corner.

6-30-1988 County Surveyor dug to cover T. Hunter 1/4 line from south which came 8' west of CP to fence N-S-E the CP is near T. Fraser location, found 9" x 10" square post mark going 1' down into clay mark is 23.5 west of trav nail and 3.1' north of T.N. Dug to bottom of post mark below it found smaller 2-1/2" dia mark running smaller as it went down. Bottom of mark which is 6" conc down 2.2' deep. Dug from 6' west of CP to 12' west and 3' N and S of fence line east. Found stone lying flat at surface 4' W of corner post stone was 1-1/2"x8"x14".

6-30-1988 County Surveyor 1/16th corner south of 1/4 corner 18-19 107-11. Dug for T. Hunter stake found nothing from S east of T.N. to 9' east and from 1' North of T.N. to 4' south. The west edge of the hole was 2-1/2' deep to clay and the east edge was 1' deep to clay line from south would be ± 8' east of T.N. Line to mark found at 1/4 corner 18-19 would be ± 7' east of t.n.

3-1991 Roger Brand & Assoc. set pipe with cap on E-W section line at intersection of 1/4 line from north in section 18 this matches the work of the County Surveyor's traverse. The corner falls ± 1' northerly of CP to fence N-S-E

7-23-2003 County Surveyor found pipe with cap up 0.3' in good condition. Took local ties and removed pipe. Set CIC on a 4.0' telspar pipe up 0.2'.

9-29-2010 County survey crew found cast iron cap on telspar pipe at surface in good condition.