Certificate of Location of Government Corner

ID#: 711905 **Description:** W SEC COR 19 30 71 **Date Set:** 9/8/86 **County:** Olmsted

Section: 19 **Township:** 107N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is up 0.2'
The corner falls 0.5' east of N-S fenece and southe of large tree used as old fence corner post
Sign on CP 1 1/2' south
County Survey Disk in E side fence post N 1.66'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes. John Ball, Deputy Survyeor North between sections 25 and 30 80.00 chs Set post for corner to section 19, 30, 24, 25 14" burr oak S 12° W 70 lks 10" burr oak N 68° W 173 lks 8" burr oak S 77° E 62 lks 12" burr oak N 15° E 175 lks

5-1889 Thomas Fraser, County Surveyor, (Page 431, No 418). No fence ever put up, found stone lying on ground said to have been brought to where stake stood, to replace it but had never been set. Dug in area and found rotted stake avered to be Gov't stake by old settlers, set stone 2½" x 6"-1" x 16". Set 1/16 corner east stone 10" x 17" x 22" at 20.257 chs then 19.957 chs to quarter corner.

6-1893 William Fraser, Deputy County Surveyor, (Page 514, No 481) Found stone set by Thomas Hunter? Measured north 79.85 chs set temporary point midway and on line.

1941 County Highway Department (Book 146, Page 56) found 1/16 stone east.

9-4-1986 County Surveyor, dug at fence corner to fences north, south, and east, on north side of corner post found 2½" x 6"-1" x 14" limestone set point down. Dug further found several lime-stone pieces, down 18" found limestone 4½" x 1½" top, 4½" x 3½" bottom, 16" long, a few tenths east of upper stone. Dug further found 1½" x 6" x 15" (average width 2½") lying flat
could find no mark where it might have stood. Found clay down 12", so deepest stone dug well into clay.

9-8-1986 County Surveyor, set telspar pipe with C.I.C. at location of deepest stone found 9-4. Dug all three stones in on west side of monument.

1-4-2011 County survey crew found cast iron cap on telspar pipe in good condition.