Certificate of Location of Government Corner

ID#: 712205 **Description:** SEC COR 21 22 27 28 71 **Date Set:** 6/21/2011 **County:** Olmsted

Section: 22 **Township:** 107N **Range:** 11W **Monument Description:** Brass plug in concrete road

Reference Ties:

The corner falls 0.2' east of centerline crack of CSAH 10 and in centerline of CR 107
The monument is at the surface
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes: Wm. A. Jones, set section corner post 80 chs north of 27-28-33-34. Corner in enters county road #10 N-S, Twsp road E-W. Common lands on N&S sides corner elev 1132 corner in high fairly level area. Bov meas west 80.06 east 79.95.

4-1898 Wm. Fraser (P.625 No.567) corner gone, dug extensively pioneers never saw or knew anything about corner. Tree rows planted east and west of corner area planted without any knowledge of their north south location. Set stone as corner on meas below. Meas from 1/4 22-27 (stone set 4x6x16 in place of stake found) W to 1/4 21-28 (stone found in center road) 79.68-1/2 5259.2. Set corner at 39.87 W 2631.42 39.89-1/2 E 2627.79. Meas from 1/4 21-22 stone found south to S 33-34 (stake found and stone 4x7x27 set in its place) total 199.67-1/2 13,178.55 or 39.93-1/2 2635.71 per 1/2 mile. Corner came 45 lks 29.7' north of row true running east of south side road 46 lks 30.36' south of row trees running east on north side road and 36 lks 23.76' west of tree row running south on east side road. Meas east from corner set 39.81-1/2 2627.8' west 39.87 2631.4', meas north and south 39.93-1/2 2635.71. 16 south set stone 1/2 way between NW 27 and W 1/4 27 meas or 19.96-3/4 1317.85' not on N-S line only N-S meas came on east side of road in line 3 pine trees running east.

1945 County Highway Department set 2x2 hub assumed. Sp D PP SW 36.6, Sp D PP SE 55.05, steel corner post of fence NE 42.48.

10-16-1974 County Surveyor set 1/2" square drag tooth by prorating W. Fraser 1898 survey.

3-7-2007 County Surveyor found p.k. nail that was set from ties at surface. Took local ties and removed. Found drag tooth down 0.4' in good condition. P.P. SW & C.P. SE now gone. Bottle cap in PP NE there, but did not check due to high snow banks.

9-2-2008 County Surveyor found 1/2" drag tooth down 0.4' in good condition and removed.

10-3-2008 County Surveyor set 1" square pipe w/cap at surface at drag tooth position.

6-21-2011 Construction of CSAH 10 destroyed existing monument. County survey crew set a brass plug in concrete road using previous GPS coordinates.