Certificate of Location of Government Corner

ID#: 712406 **Description:** 1/4 SEC COR 23 24 71 **Date Set:** 7/23/2009 **County:** Olmsted

Section: 24 **Township:** 107N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is down 0.4'
The corner falls 2' south of centerline of E-W twp road and 1' east of centerline of N-S twp road
County highway disk in W side PP #1114 SSE 79.75'
County survey disc number 42638 in southeast side of power pole, NE, 43.46'
This corner is located by GPS measurement

Corner History:

9-1853 Gov't Notes William Jones, Deputy Surveyor North between sections 23 and 24. 40.00 chs. Set a quarter section post in a mound of earth and sod and deposited charcoal. Made trench and pits and planted osage orange seed East and West of trench.

10-1896 William Fraser (P.679 No.604), County Surveyor, found stone in center of road set by settlers in place of Gov't stake.

5-1900 Robert Fraser (P.679 No.604), County Surveyor, found stone in center of road. Left as found.

9-30-1974 County Surveyor dug with backhoe and found stone 4' deep in 4-way intersection. Set ½"X30" rod on the East side of the stone and set a CIM over all.

7-20-2009 County Surveyor found CIM down 0.8' w/head broken.

7-23-2009 County Surveyor found CIM down 0.8' w/head broken, removed. Found stone with iron rod directly below. Removed and replaced with a cast iron cap on telspar pipe.

4-27-2012 County survey crew found cast iron cap in good condition.