Certificate of Location of Government Corner

ID#: 712709 **Description:** SEC CEN 27 71 **Date Set:** 8/18/1977 **County:** Olmsted

Section: 27 **Township:** 107N **Range:** 11W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.

Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls between 3 posts for fences N-S-E-W
The monument is down 0.1'
Post w/sign 1 1/2' north
This corner is located by GPS measurement

Corner History:

4-25-1898 William Fraser, County Surveyor, (Book A, Pages 625-626, No. 569), set stake and iron at intersection of quarter lines. At W 1/4 used north-south measure only. At S 1/4 used fence and tree line. 1/16th North set stone midway and on line at 19.88 3/4 chains (1312.58').

5-24-1900 Robert Fraser, County Surveyor, (Book A, Page 677, No. 602), found and used iron stake with wagon hub. 1/16th East set a dry oak stake and put a boulder about a foot long on the west side midway and on line at 19.96 1/2 chains (1317.69').

8-18-1977 County Surveyor dug 5' E-W by 7' N-S to 3.5' deep to clay at double line and measure from North 1/4 Corner over 1/16th North. Found nothing. Set cast iron cap on telspar pipe this position. Corner falls in center of 4 corner post complex to fences N-S-E-W.

6-24-1991 Roger Brand & Associates found and used cast iron cap on telspar pipe.

1-14-2009 County Survey Crew found cast iron cap on telspar pipe down 0.1' in good condition and measured its position using GPS.

2-23-2010 Joel Thoreson, County Surveyor, used cast iron cap on telspar pipe for Olmsted County Right of Way Plat Nos. 180 & 181.

4-30-2018 Mark Severtson, County Surveyor, recommends using the monumented center of section based on historical use of this position.