Certificate of Location of Government Corner

ID#: 712905 **Description:** SEC COR 29 30 31 32 71 **Date Set:** 8/31/2012 **County:** Olmsted

Section: 29 **Township:** 107N **Range:** 11W **Monument Description:** Cast Iron Cap on Telspar Pipe

Reference Ties:

The monument is at the surface.
The corner falls on west side of stream.
Ties to 3/4" rod 158' North of corner position
Rod lies 8' north of centerline
Ties to 3/4" rod 72.98' North of corner position
This corner is located by GPS reference stations "Loftus A & B"

Corner History:

1853 Gov't Notes William A. Jones, Deputy Surveyor North between sections 31 and 32. 80.00 chs Set section corner post. 18" Br. Oak N18W 75 lks. Made trench.

10-6-1874 Tom Hunter (Book A, P. 262 No. 261), County Surveyor, measured east line of Section 31 and found stake by fence avered by a Mr. Bush as mound and stake location. Found stake nearly 24" long and flattened. Placed stone at stake location.

6-14-1881 John Fraser (Book A, P. 368 No. 359) found Gov't corner and made new bearing trees.

5-14-1889 Thomas Fraser (Book A, P. 431 No. 418) states stone had washed out but was tied to the fence. Tested location by John Fraser's bearing trees and it was within 3 in. Set stone 3" x 12" x 24".

10-23-1974 County Surveyor found that corner had been washed out (location in a large ditch). Projected the east line of Section 31 north and doubled the distance between the E 1/4 Corner Sec. 31 and The S.E. Sec. Cor. 31 for corner location as per Tom Hunter.

11-11-2002 Massey Land Surveying set 1 1/2" pipe at county position from ties.

3-14-2005 County Surveyor found 1 1/2" pipe up 0.1' in good condition.

3-16-2005 County Surveyor found 3/4" reference rod 158' north down 0.2' bent and leaning.

8-31-2012 County survey crew found 1 1/4" pipe in good condition. Removed and replaced with 4' telspar pipe with cast iron cap.