Certificate of Location of Government Corner

ID#: 713105 **Description:** SW SEC COR 31 71 **Date Set:** 11/29/94 **County:** Olmsted

Section: 31 **Township:** 107N **Range:** 11W **Monument Description:** 5/8" copper plug w/punch mark

Reference Ties:

The corner falls 0.1' north of centerline of CSAH 9, in centerline of twp road south and 2' east of centerline of twp road north
County Survey Disk in PP SE 63.83'
County Survey Disk in PP NE 67.19'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, John Ball, Deputy Surveyor North between sections 6 and 1. 80.00 chs. Made mound with trench and planted osage orange seeds. Drove charred stake as corner.

10-1874 Thomas Hunter (P. 262 No. 261), County Surveyor, found stone planted by settlers.

1875 State law required that a monument be placed at township corners.

8-1887 Hunter (P. 419 No. 408) found engraved township monument set by law.

6-1893 William Fraser (P. 517 No. 483), County Surveyor found township corner.

9-1927 County Highway Dept. (Book 48 P. 31) found 10"x10"x30" stone monument in place.

5-1935 County Highway Dept. (Book 75 P. 63) found boulder with "+" at N.E. Sec. 1 Eyota.

7-1938 County Highway Dept. (Book 94 P. 5) found boulder stone with cross

5-25-1973 Roger Brand, County Surveyor, Found bottom portion of the township monument. Set a C.I.M. over the monument.

4-13-1979 County Surveyor found C.I.M. in good condition.

6-3-1993 county highway department Took grading ties to C.I.M. before construction of CSAH #9.

11-30-93 county highway department set 3/8" Iron as Corner in crushed rock surface of CSAH #9.

11-29-94 County Surveyor set 3/4" Copper Rod in Concrete Surface of CSAH #9 as final corner.

11-9-2006 County Surveyor found 5/8" copper plug w/punch mark at surface in good condition.

3-6-2007 County Surveyor found 5/8" copper plug w/punch mark at surface in good condition.