Certificate of Location of Government Corner

ID#: 713106 **Description:** W 1/4 SEC COR 31 71 **Date Set:** 8/20/2010 **County:** Olmsted

Section: 31 **Township:** 107N **Range:** 11W **Monument Description:** Cast Iron Cap on Telspar pipe

Reference Ties:

The monument is down 0.1'
The corner falls 3' west of CP to fences north and east
Bottle cap in E side TP S 6.85'
Sign on CP 3' east
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, John Ball, Deputy Surveyor North between sections 31 and 36. 40.00 chs. Set quarter section post. Bur Oak S86°E 217 lks. Bur Oak N4½°W 430 lks.

10-1874 Thomas Hunter (P. 262 No. 261.), County Surveyor, states ¼ post missing and both bearing trees grubbed and gone. No trace could be found. Ran a straight line between section corners and set a stone 3"X4"X18" midway and on line.

6-1893 William Fraser (P. 517 No. 483), County Surveyor, found stone.

5-23-1973 County Surveyor dug and found recorded stone. Lowered stone and placed an iron rod under it and set a C.I.M. over all.

9-25-1992 County Surveyor found C.I.M. with top broken off. The rest of the monument seems to be in good condition.

5-15-2007 Roger Brand reported head missing but monument in good condition.

8-20-2010 County survey crew found CIM with broken top and replaced with a cast iron cap on telspar pipe