Certificate of Location of Government Corner

ID#: 713204 **Description:** S 1/4 SEC COR 32 71 **Date Set:** 11/29/1994 **County:** Olmsted

Section: 32 **Township:** 107N **Range:** 11W **Monument Description:** 5/8" copper plug w/punch mark

Reference Ties:

The corner falls 0.1' north of centerline of CSAH 9, 8' east of centerline of field entrance north, 23 1/2' west of centerline of field entrance south and in line with fence south
County highway disk in PP WSW 129.23'
This corner is located by GPS measurement

Corner History:

9-1853 Gov't Notes: Set post and drove charred stake, built mound with trench.

9-1929 County Highway Department (B.48 P.27) assumed corner. Blazed tree S 32.3, SW corner south headwall culv SW 12.8. B.94 P.46 no recongnition of corner 1938 fence south at sta 158 + 20 fe W S 38' S sec cor west 131 + 80.75 or 2639.25 then to sta 184 + 64.35 or 5283.6 for mile.

7-3-1970 County Surveyor, no apparent sign of where corner could be except boundry fence south.

10-23-1992 County Surveyor dug with backhoe for gov't corner at M&L between section corners. There was 6" of blacktop on C.R. 9. We dug 5-1/2' deep to clay there was 3' of black dirt below oldest road, a stake could never have reached clay it was probably gone in road const.

6-1993 county highway department took grading ties to M&L position of 1/4 corner before construction of CSAH #9.

12-10-1993 county highway department set 3/4" iron as corner in crushed rock CSAH #9.

11-29-1994 county highway department set 3/4" copper rod in concrete CSAH #9 as final corner at M&L position between section corners.

3-15-2005 County Surveyor found 5/8" copper plug w/punch mark at surface in good condition.

11-9-2006 County Surveyor found 5/8" copper plug w/punch mark at surface in good condition.

3-6-2007 County Surveyor found 5/8" copper plug w/punch mark at surface in good condition.