Certificate of Location of Government Corner

ID#: 713305 **Description:** S SEC COR 32 33 71 **Date Set:** 11/21/94 **County:** Olmsted

Section: 33 **Township:** 107N **Range:** 11W **Monument Description:** 5/8" copper plug with punch mark

Reference Ties:

The corner falls 0.2' north of centerline of CSAH 9 and in line with fences north and south
County Survey Disk in PP #42158 ESE 97.15'
This corner is located by GPS measurement

Corner History:

9-1853 Gov't Notes John Ball, Deputy Surveyor West between sections 4 and 33 80.00 chs. Set post and drove charred stake corner to sections 4.5, 32, and 33 Built mound with trench per instructions. Planted SE Osage Orange seeds, NE apple seeds.

9-29-1938 County Highway Department (Book 94 Pg 7) Set bridge spike down 1.5'. Took Rp's spike in tel. pole NE 41.8'. Spike in willow stump SE 63.75'. Spike in cottonwood SW 36.65'.

5-23-1939 County Highway Department (Book 94 Page 7) Retied bridge spike, spike in fence post N 73.8, Hub NE 92.6'.

7-2-1970 County Surveyor looked for bridge spike set in 1939, and dug for post stub N 73.8' found nothing.

11-2-1988 County Surveyor dug with backhoe in blacktop C.R. #9. Found bridge spike with hub beside 2.5' deep. Dug further found 2 stakes side by side 3.8' deep, found 5" diameter post hole 0.8' SW of stakes. The newer of the 2 stakes measured 17" long, the older had 3" left, but black mark ran 12" into clay. Backfilled hole and set spike at surface at location of oldest stake found.

5-17-1989 County Surveyor set 1" square pipe with cap over old stake location. Corner lines with N-S fence and falls 0.3' north of centerline C.R. #9.

6-1993 county highway department took grading ties to square pipe with cap before construction of CSAH #9.

12-10-1993 county highway department set 3/4" Iron in crushed rock surface CSAH #9.

11-21-1994 county highway department set 5/8" copper plug in concrete surface CSAH #9.

11-7-2005 County Surveyor found 5/8" copper plug with punchmark at surface in good condition.

3-7-2007 County Surveyor found 5/8" copper plug with punchmark at surface in good condition.