# Certificate of Location of Government Corner

**ID#:** 713306 **Description:** 1/4 SEC COR 32 33 71 **Date Set:** 11/7/2005 **County:** Olmsted

**Section:** 33 **Township:** 107N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

**Reference Ties:**

Post w/sign 1 1/2' north
This corner is located by GPS measurement

**Corner History:**

8-1853 Gov't Notes, William A. Jones, Deputy Surveyor North between section 32 and 33 7.50 chs. Top of ridge 20.00 chs. Enter Valley E and W 30.00 chs. Leave Valley E and W 40.00 chs. Set quarter section post Burr Oak 10 lks. N 41º W Oak 12 lks. N 8º E

11-22-1988 County Surveyor dug with backhoe on east side of 48" cottonwood tree, which had been terminal for fence east and south for years according to land owner to the S.E. We dug
8' x 8' 3' deep found nothing.

5-22-1989 County Surveyor talked to Mr. Palmby, who owns the SW 1/4 of Section 33, and rents all land around 1/4 corner. He claims E-W fence ran on north side of cottonwood tree, he took out fence 5 or more years ago. Dug on north side of cottonwood found nothing.

5-23-1989 County Surveyor set telspar pipe with cast iron cap at occupation line avered to by Mr. Palmby. Corner also midway N-S between section corners.

11-7-2005 County Surveyor found cast iron cap on telspar pipe at surface bent to the east. Removed bent telspar pipe and set 6' telspar pipe w/cast iron cap down 0.9'. Set post w/sign.