Certificate of Location of Government Corner

ID#: 713404 **Description:** S 1/4 SEC COR 34 71 **Date Set:** 9/10/98 **County:** Olmsted

Section: 34 **Township:** 107N **Range:** 11W **Monument Description:** 5/8" copper plug w/punch mark

Reference Ties:

The corner falls 0.1' north of centerline of CSAH 9 and 6 1/2' east of fence north
County Survey Disk in PP SW 139.40'
County Survey Disk in PP SE 155.89'
Ref. pipe N 84.97'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, John Ball, Deputy Surveyor West between sections 3 and 34. 40.00 chs. Set post for quarter section corner. Burr Oak 10 in. N53°E 184 lks. Dug trench per instructions.

7-1857 In the survey of Road No. 56, E.P. Bircher, Surveyor, and Thomas Hunter, Deputy, measured from the S.E. corner 36, T107N, R11W west for 8 miles and call for the quarter post at this corner and the section posts east and west.

4-1898 William Fraser, County Surveyor, (Book A P. 625 No. 567) found a wood stake in the center of the road at S. Sec. Cor. 33-34 and set a 4"x7"x27" stone at its location.

1941 County Highway Department (C.H.D. Book 125 P. 4) records a stone monument at S. Sec. Cor. 34-35.

1974 County Surveyor found the stone recorded by Fraser at S. Sec. Cor. 33-34.

7-6-1977 County Surveyor dug at S. Sec. Cor. 34-35 and found a 6"x10"x21" limestone. The corner came 2' West of the fence North and in line with the fence south.

7-7 & 8-22 County Surveyor dug for the S. ¼ Cor. 34 but did not find
1977 anything.

8-26-1977 County Surveyor set a ¾" x 20" bolt as the corner on line between S. Sec. Cor. 33-34 and S. Sec. Cor. 34-35 and at the prorated location as per the 1857 road survey. The corner came 6' East of the fence North. We projected the line from the N. ¼ Cor. 34 over the corner post at the center 34 and the line came 5' East of the fence North. We also projected the line from the N-S fence at the S. ¼ Cor. 3 over the N-S fence near the Center 3 and this line came 10' East of the fence North at the S. ¼ Cor. 34. Took reference points to the corner.

6-21-1978 County Highway Dept. dug out the corner while patching the road. Set a C.I.M. over a ¾" x 20" rod from the reference points taken in 1977.

7-31-1995 County Surveyor found CIM in good condition. Referenced corner before construction of CSAH 9.

7-15-1998 County Surveyor drilled hole in concrete surface CSAH 9 from 1995 reference

9-10-1998 County Surveyor set 5/8" copper plug w/punch mark at 1995 reference location.

11-7-2005 County Surveyor found 5/8" copper plug w/punch mark in good condition at surface.

3-6-2007 County Surveyor found 5/8" copper plug w/punch mark at surface in good condition.