Certificate of Location of Government Corner

ID#: 713406 **Description:** 1/4 SEC COR 33 34 71 **Date Set:** 6/21/2011 **County:** Olmsted

Section: 34 **Township:** 107N **Range:** 11W **Monument Description:** Brass plug in concrete road

Reference Ties:

The corner falls 0.2' east of centerline crack of CSAH 10 and in line with fences east and west.
The monument is at the surface.
This corner is located by GPS measurement

Corner History:

9-1853 Gov't Notes William A. Jones, Deputy Surveyor North between sections 33 and 34 30.06 chs. A stream 15 lks wide curse east 40.00 chs. Set a quarter section post in mound of earth and sod, deposited charcoal, made trench and pits, planted osage orange seeds E and W of trench.

10-1976 Harry S. Johnson and Co. set 5/8" pipe after finding 3 different nails in same location but at different elevations, the deepest one down 15".

8-23-1977 County Surveyor dug 1.0' south 0.7' north and 4.0' east of 5/8" pipe set by Harry S. Johnson Co. to 3.0' deep. Found nothing conditions good black dirt beneath old road. Reset nail at surface at location of 5/8" pipe.

5-19-1989 County Surveyor set 1" square pipe with cap at location of 5/8" pipe set by Harry S. Johnson and Co. in 1976.

11-8-2005 County Surveyor found 1" square pipe w/cap down 0.2' in good condition. Corner post has been replaced, tie in PP ok, did not check distances.

6-21-2011 Construction of CSAH 10 destroyed existing monument. County survey crew set a brass plug in concrete road using previous GPS coordinates.