Certificate of Location of Government Corner

ID#: 713504 **Description:** S 1/4 SEC COR 35 71 **Date Set:** 6/24/99 **County:** Olmsted

Section: 35 **Township:** 107N **Range:** 11W **Monument Description:** 5/8" copper plug w/punch mark

Reference Ties:

The corner falls 0.1' south of centerline of CSAH 9 and 4' west of fence south
County Survey Disk in top center wood CP S 59.57'
Ref pipe SSE 59.17'
This corner is located by GPS measurement

Corner History:

9-1853 Gov't Notes John Ball Deputy Surveyor - West between sections 2 and 35. 40.00 chs. Set ½ post10" Bur Oak N 72° E 106 links10" Bur Oak N 45° W 223 links

10-1902 William Fraser, County Surveyor (P. 26 Bk. B) Surveyed in section 35. Could not find south ¼ corner 35 set temp stake midway and on line between south section corner 34, 35 and south section corner 35, 36.

8-22-1977 County Surveyor dug at south ¼ corner 35, and ¼ line from the north and in centerline of east-west road 3' north and 3' south dug 1½' deep found nothing.

9-13-1988 County Surveyor dug again at south ¼ corner 35 2' west and 10' east of N-S ¼ line and from south edge of (1977 dig) south 1½', found possible stake mark on west end of hole.

9-19-1988 County Surveyor at south ¼ corner 35 set 1" square pipe and cap at intersection of north-south ¼ line of Sec. 35 and section line from S.W. 35 section corner to S¼ corner 36.

7-31-1995 County Surveyor - Referenced pipe with cap before construction of CSAH #9.

7-15-1998 County Surveyor set P.K. Nail in concrete 0.1' South of centerline crack of CSAH 9 from 1995 reference.

6-24-1999 County Surveyor set 5/8" copper plug w/punch mark at surface.

12-12-2006 County Surveyor found 5/8" plug w/punch mark at surface.

3-6-2007 County Surveyor found 5/8" copper plug w/punch mark at surface in good condition.