Certificate of Location of Government Corner

ID#: 720104 **Description:** 1/4 SEC COR 1 12 72 **Date Set:** 11/13/1981 **County:** Olmsted

Section: 01 **Township:** 107N **Range:** 12W **Monument Description:** 4"+ diameter solid shaft set in concrete

Reference Ties:

The corner is the CP to fences N-S-E
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes William A. Jones, Deputy Surveyor West on true line between Sections 1 and 12. 39.99 1/2 chs. Set a quarter section post at average distance from which a Burr Oak 6 in. diam. N18ºW 50 links. Made a trench. 79.99 chs. To Section Corner.

6-10-1902 Robert Fraser, Deputy County Surveyor, (Book A, Page 708, No. 622 and Old Fieldbook 10, Page 42) "could find nothing. Drove stake on line and midway between E (SW corner 1) and G (SE corner 1). Put Stone." He used this corner to set the 1/16 North, a stake and stone, midway (19.98&3/4 chs.) and on line to the Center 1, a stone set at intersecting 1/4 lines.

6-11-1902 Robert Fraser (Book A, Page 709, No. 623 and Old Fieldbook 10, Page 44) used the corner set in Survey No. 622 to set the 1/16 South, a stone, midway (19.91&1/4 chs.) and on line to the Center 12, a temporary stake (a Mr. Richardson said he would put a stone), set at intersecting 1/4 lines.

8-16-1972 Mr. Evans, who owns the NE 1/4 Sec. 12, told the County Surveyor that when he set the large corner post in the concrete at his NW farm corner he found over 3' deep a limestone with Cross, covered to that depth by soils from adjacent fields on slight slope. He said he set the corner post exactly on the cross on the limestone.

10-28&29-1981 County Surveyor dug at the Center 12 and found a 2"x6"17" limestone standing 2' deep. (This stone is .17 South and 2.09 East of the intersection of the 1/4 lines by electronic traverse computation when all 1/4 Corners are set). Dug at the 1/16 North of the Center 12 but did not find anything. Dug around the 4"+ solid shaft corner post at 1/4 corner 1-12. Found shaft in concrete with 3' diameter and 3 1/2' deep. Impossible to look under. Cement dug well down into clay. Dug up to 5' East under the fence to cover the line from the S 1/4 corner 12 over the stone found at the Center 12 but did not find anything.

11-12-1981 County Surveyor dug at the Center 1 and found a 6"x9"x13" boulder standing 2' down and 2.7 North of the angle iron corner post to fences N-S-W. Set a 5/8" re-rod on the East side of the stone. (This stone .83 South and .26 West of the intersection of the 1/4 lines by electronic traverse computation after all 1/4 corners are set.) Dug at the 1/16 South of the Center 1 and found an 8"x8"x20"+ boulder standing 2' deep. Set a 1/2" re-rod on the South side of the stone. (This stone 1.42 North and .27 East of the calculated corner hereafter all 1/4 corners are set.)

11-13-1981 County Surveyor accepted the 4"+ diameter solid shaft set in concrete and used as the corner post to fences N-S-E as 1/4 corner 1-12. This shaft fits the line from the N 1/4 corner 1 Over the stones found at the Center 1 and the 1/16 South of the Center 1 closely and the top center of the shaft is just .05 North and .26 West of a point midway and on line between the section corners by this electronic traverse computation.

3-16-2010 County Surveyor found shaft in good condition.