Certificate of Location of Government Corner

ID#: 720105 **Description:** SEC COR 1 2 11 12 72 **Date Set:** 7/9/1973 **County:** Olmsted

Section: 01 **Township:** 107N **Range:** 12W **Monument Description:** Cast Iron Cap on Telspar Pipe

Reference Ties:

Monument falls 5' E of N-S twp road and 4' S of cenrline twp road west
Conc. nail in PP #33151 NNW 85.68'
Cross"+" in conc. headwall SW 36.81'
RR spike in W side 22" Pine SSE 82.67'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes William Jones, Deputy Surveyor North between sections 11 and 12. 80.00 chs. Set section corner post. Made mound of earth and sod, trench, pits, and deposited charcoal.

10-1889 Thomas Fraser (P.436 Book A), County Surveyor, found spade blade with 1' of handle set by a Richardson where original corner stood. Set stone 3 1/2" x 8"x20" by its side.

6-1893 William Fraser (P. 518 Book A) found stone P. 436.

6-1902 Robert Fraser (unrecorded survey in field book No. 10), County Surveyor, found boulder stone with stone beneath.

6-29-1973 County Surveyor dug and found stone with old spade on west side and boulder over it.

7-9-1973 County Surveyor set C.I.M. over 1/2" rod over stone.

3-17-2010 County survey crew found cast iron monument with top broken and leaning to the east down 0.8. Removed cast iron monument and found 5/8" iron rod down 2.7' in good condition. Set 3' telspar pipe with cast iron cap down 0.5' over rod.