Certificate of Location of Government Corner

ID#: 720204 **Description:** 1/4 SEC COR 2 11 72 **Date Set:** 7/21/2003 **County:** Olmsted

Section: 02 **Township:** 107N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in centerline of E-W twp road and 9' west of centerline of field drive north
County Survey Disk in PP #46553 S 26.85'
This corner is located by GPS measurement

Corner History:

Gov't Notes W.A. Jones 1853 East random between 2 & 11 40.00 set a temporary section post West on true line between Sect. 2 & 11 bar 8" 58' E 40.01-1/2 set a section post in mound of Earth- sod deposited charcoal. Made trench & pitts planted Osage orange seed N & S of trench.

10-1889 T. Fraser P 436 No. 423 set boulder 2' long M & L 39.87-1/8 (2631.5) 1/16 west set stone about 2' long M & L 19.93-9/16 (1315.75)

6-1893 W Fraser P518 No. 484 found stone P 436. - 1/16 south set stone 2x6x20 M & L 19.88-1/2 N22'E (1312.41) to stone at center sec. 11 2-1/2x5x24.

6-29-1973 County Surveyor found 1/16 corner E found 4" "square" L stone over 2' down all in clean clay indicating clay very shallow and road ran deep when stone set. set nothing prior to finding 1/4 2-11 or 1-2-11-12. set 40 D Sat edge road. 9.75 nail W. 30.0 (could get lost) - dug entire area at 1/4 2-11 to clay which is old road top. Found nothing must reset on section line M & L or from South.

7-9-1973 County Surveyor after finding 1-2-11-12. 7-5-73 dug again at 1/4 2-11 but road long gone to clay. 7-10 Re meas. S line Sec. 2 accepting line ran 7-9-73. set 1/2"x30" reinf. rod exactly M & L 2630.45 corner comes in center road 2' east of fence north. Did not set CIM as will check line & meas. south at later date (changed rod due to error in calculations).

7-21-2003 County Surveyor found 1/2" rod down 0.5' in good condition. Took local ties and set CIC on a 5.0' telspar pipe over rod down 0.5'.

3-16-2010 County Surveyor found cast iron cap on telspar pipe down 0.5' in good condition.