Certificate of Location of Government Corner

ID#: 720205 **Description:** SEC COR 2 3 10 11 72 **Date Set:** 7/22/2003 **County:** Olmsted

Section: 02 **Township:** 107N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 2 1/2' north of centerline of E-W twp road and 76' west of centerline of Little Valley Substation 15 driveway south
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes William A. Jones 20.00 leave timber E & W. 40.00 Set a section post in mound of earth and sod deposited charcoal made trench and pits planted osage orange seed E & W of trench.

10-1889 Thomas Fraser P436 No. 423 found stone set 15 years before this survey avered to be correct. -16E set stone 2' long M & L 19.93 6/16 1315.75 set stakes for fencing north from above 1/16 corner. Note this 1/16 fence at north end. set this survey only 1306.5 east of 1/4 stone found Record. 1316.53.

5-1890 Thomas Fraser P. 441 No. 427 found stone sest by Hillman found P.436 Meas. N to corner re-set 39.86-1/2 2631.09 -16 W set stone M & L 19.89 -1/2 1313.07 set stakes for line north of this 1/16 (Now MHD 42).

6-1893 Wm Fraser P 518 No. 484. found stone P. 436. -15 S. set unmarked stake M & L 19.90-1/2 1313/73.

6-18-1970 County Surveyor Meas. electronic and line from nail set in 1/4 2-11 area in line fences N & S. RP to this nail 47.85 NE to conc. nail in corner post 40.11 SE to conc. nail in gate post. Meas. west elec. to nail in line fence N. 1313.78 Rc 1315.75 con't. meas. west to stone found at SW 2 1313.78 or 2629.63.

8-16-1972 County Surveyor dug with d7 cat owned by Forrest Wharton. found 1" square iron just south of 6"x9" top limestone about 2-1/2' deep, left iron & stone as found. road really torn up., may have set temp iron, but check.

6-29-1973 County Surveyor found 1/16 stone east down 2'+- in clean clay a 5"+- "square" limestone very vertical and long dug for 1/4 2-11 but found nothing. will try for 1-2-11-12.

12-7-1990 Roger Brand and Associates found and used iron rod as corner in survey of SE 1/4 Sec. 3.

7-22-2003 County Surveyor found 1/2" rerod down 0.3' in good condition. Removed 1/2" rerod and found 6" x 9" x 30" limestone with 1" square iron on south side down 2.1' in good condition. Removed stone and iron and set 6' telspar pipe w/cast iron cap down 0.5' at 1/2" rerod position.

3-16-2010 County Surveyor found cast iron cap on telspar pipe down 0.5' in good condition.