Certificate of Location of Government Corner

ID#: 720206 **Description:** 1/4 SEC COR 2 3 72 **Date Set:** 10/1/2010 **County:** Olmsted

Section: 02 **Township:** 107N **Range:** 12W **Monument Description:** Cast iron cap on telspar pipe

Reference Ties:

The monument is up 0.4'
The corner falls just north of fence corner post of fence south
Post with sign is south 2'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes Jones Set 1/4 Section post on line at 40.15 (2629.9 from north) 6" Bur Oak N27 W 77 lks.
6" Bur Oak S15 E 158 lks.

10-10-1889 T. Fraser P. 436 No. 423 found large stone partly buried seeming to be where orig corner should be. Ran N-S line which passed. 4" west of center stone used this point to set halfway point east for sub dividing line south. 1/16 east set stone 3-1/2x6x28 M & L 19.94-3/4

5-16-1890 T. Fraser P. 441 No. 427 had Mr. Hillmans notes on this line which stated he set stake M & L while gov't notes demand that mile be 80.15 which actual meas. is 79.88-1/2 -Set stone 3x9x24 at this point on N-S line at Gov't proportionate measure.

8-15-1972 County Surveyor found limestone just north of large fence corner post of fair fence south. Fence east not so good, fence west down no fences north, common land.

3-25-1992 McGhie & Betts found and used stone.

4-7-1992 Roger Brand and Associates used stone as corner in survey of NE 1/4 sec. 3.

4-6-2006 Massey Land Surveying found and used limestone for survey in SW 1/4 section 2-107-12

10-1-2010 County survey crew found stone in good condition. Removed the stone and replaced it with a 5' telspar pipe with cast iron cap.