Certificate of Location of Government Corner

ID#: 720305 **Description:** SEC COR 3 4 9 10 72 **Date Set:** 6/12/2008 **County:** Olmsted

Section: 03 **Township:** 107N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is down 0.1'
The corner falls 1' north of centerline of E-W twp road
Gov't Bearing tree (30" Burr Oak) N 31° 45' E 226.0'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes John Ball, Deputy Surveyor North between sections 9 and 10. 80.00 chs. Set section corner post. Burr Oak 10 in. N30°E 344 lks. Burr Oak 14 in. S22° W 266 lks. Burr Oak 6 in. S18°W 261 lks.

5-1890 Thomas Fraser (P. 441 Book A), County Surveyor, found large stone in road claimed set in place of stake. Used as corner stone. Meas. east 39.78-5/6 (2626.03) to temp point set M & L. Meas. north 39.88-1/4 (2632.25) to stake set prop distances.

10-1894 William Fraser (P.553 Book A), County Surveyor, found stone.

3-19-1973 WHKS crew found stone in road.

6-22-1973 County Surveyor dug down with tractor north side by WHKS's iron and found positive witness tree (R 10"B.o. N 30° E 344L 227.04).

7-5-1973 County Surveyor set C.I.M. over stone.

12-4-2006 County Surveyor found CIM down 0.9' leaning west.

6-11-2008 County Surveyor found CIM down 0.9' leaning west. Removed CIM and found 5" x 8" x 18" stone down 2.7' in good condition. Removed stone.

6-12-2008 County survey crew set 7' telspar pipe w/Cast Iron Cap down 0.4' at stone position.

9-16-2010 County survey crew found CIC in good condition